

AGREEMENT FOR SNICE SEASONAL TEMP FOR WINTER OPERATIONS

WORK TO BE PERFORMED BY THE SNICE SEASON TEMP

Job Code – 026811

The following tasks are the basic job functions that must be performed by a SNICE Seasonal Temp for the effective operation of dump trucks and equipment during a winter weather event. **These temporary employees WILL be required to take a post-offer drug test, but will NOT be required to take a post-offer physical test. These temporary employees will be paid at the rate of \$20.50 per hour and are eligible for overtime. This position is not eligible for stand-by or snow premium pay and is not eligible for personal protection equipment (PPE).**

1. Perform pre-trip and post-trip inspections of dump trucks on Form 364.
2. Fill truck with fuel and DEF, if equipped.
3. Fill saddle tank and/or slip in tank with brine.
4. Operate loader to load spreader, make brine, or mix material during a storm.
5. Climb in and out of trucks and equipment.
6. Replace windshield wiper blades.
7. Clear snow/ice from lights, strobes, windshield, and spreader chute.
8. Climb ladder on side of dump truck to check load.
9. Break up chunks of frozen material in spreader.
10. Perform walk around checks during shift including checking condition of plow blades.
11. Unload material from spreader at end of storm.

The following tasks are **not** to be performed by Temporary SNICE Operators.

1. Remove or replace tailgates.
2. Load or remove spreader or anti-ice tanks from truck.
3. Mount or remove snow plow.
4. Change or assist in the changing of plow bits.
5. Change tires.
6. Install tire chains.

Signature of SNICE Seasonal Temp

Date

Supervisor

Date

c: Employee's Supervisor
 Area Superintendent
 Employee file